

# Use of a Rapid Visual Assessment to Monitor In-Stream Structure Success



**Karen Jennings and Sean Crawford**

**Coastal Resources, Inc.  
25 Old Solomons Island Road  
Annapolis, Maryland 21401  
410-956-9000**

04/07/2010 08:28




# Reasons for monitoring in-stream structures:

- **High cost item**
- **Key features of design (grade control, channel alignment)**
- **Lessons learned for future designs**
- **Early identification and remediation of problems can save money**

01/28/2010 09:42

# Traditional monitoring methods:

- **Cross Sections and Longitudinal Profiles only show a 2-D view**
- **Visual observations may be subjective - results are difficult to reproduce amongst different people involved**
- **Photos may not reveal small or obscured problems (i.e. piping)**



# Structure Performance and Failure Risk Analysis

- **Uses the Rock Cross Vane Rapid Assessment Tool (Puckett, 2007) and expands to include other structure types**
- **Focuses on failure mechanisms**
- **Guides attention to visual indications of failure**
- **Objective and repeatable**
- **Quantitative**
- **All encompassing**




**Structure Goal**




**Failure Type**



**Failure Indicators**



**Primary Causes**



**Secondary Causes**

**A failure indicator is the visual clue or observation that indicates the structure is not durable, or that it is not performing its intended function.**



**Bank undercutting and streambed scour.**



**Piping under structure boulders.**

**Includes  
restoration  
goals, not just  
durability.**

**Buried step pools are no  
longer performing the  
restoration goals of  
dissipating water energy  
or providing pool habitat.**



09/02/2011 11:10

# Failure indicators are given a numerical rating based on severity.

| Score             |                           | 0                         | 1  | 3   | 5   |
|-------------------|---------------------------|---------------------------|--|---|---|
| Failure Indicator | Arm or Side Washout       | Indicator is not present. | Less than 10% of the arms or sides have washed out (i.e. one or two boulders missing) or observable signs of boulder shifting are present.                 | 11% to 30% of the boulders are missing.   | Greater than 30% of the boulders are missing.   |
|                   | Head Cut                  | Indicator is not present. | Observable signs of boulder shifting are present, or there is slight side cutting and/or undercutting of the sill.   | Undercutting travels all the way under the sill, or the bed around the sill has begun down-cutting (as opposed to the sill simply being installed above bed elevation)  | A visible head cut has occurred and/or is migrating upstream.   |
|                   | Bank Erosion at Structure | Indicator is not present. | Vegetation has been washed off at the toe of banks and/or there are sparse patches of erosion on less than 25% of the bank area.                           | Patchy erosion covers 25% to 50% of the bank area, bank slumping has occurred but is still covered by vegetation, vegetation has been washed off the banks at half-bankfull, or there are small bank scour spots. | Most of the vegetation up to bankfull has been washed off, banks have slumped or sheared off, or there are large areas of deep scour. |
|                   | Insufficient Scour Pool   | Indicator is not present. | The pool is shallow compared to design intensions (pools were designed to have minimum depths of 1ft in step pools, and 0.75ft at cross and J-hook vanes). | The pool is shallow and there is accretion of larger material or washed out structure boulders in the pool.   | The pool is shallow with an accretion of fine material, or the pool is non-existent.  |

# Primary vs Secondary Causes of Failure

## Primary cause of failure:

**Results from stream flow and associated hydraulics.**



## Secondary cause of failure:

**Mechanisms which influence the stream flow, for example design or installation flaws.**

| Structure  | Indicator                 | Failure Score | Primary      | Secondary             |
|------------|---------------------------|---------------|--------------|-----------------------|
| Cross Vane | Arm Washout               | 3             | Undercutting | Insufficient Backfill |
|            | Bank Erosion at Structure | 5             | Side Cutting | Arms Washed Out       |
|            | Downstream Bank Erosion   | 4             | Side Cutting | Placed in a Bend      |



| Structure | Indicator                 | Failure Score | Primary                  | Secondary             |
|-----------|---------------------------|---------------|--------------------------|-----------------------|
| Weir      | Boulder Washout           | 3             | Drag and Lift or Tipping | Insufficient Backfill |
|           | Bank Erosion at Structure | 3             | Side Cutting             | Boulders Washed Out   |
|           | Downstream Bank Erosion   | 3             | Flow Directed at Banks   | Improper Alignment    |

# Failure paths can be mapped out for any type of structure.

**Table of Failure Mechanisms for Rock Cross Vanes, J-Hooks, and Step Pools (based on Puckett, 2007)**

| Failure Types                    | Failure Indicators             | Primary Causes                         | Secondary Causes                         |
|----------------------------------|--------------------------------|--|--|
| Lack of Durability               | F1. Arm Washout                | P.01 Direct Contact of Flow with Banks | S.01 Improper Alignment                  |
| Lack of Grade Control            | F2. Sill Washout               | P.02 Flow Directed at Banks            | S.02 Backed into a Pool                  |
| Lack of Bank Protection          | F3. Head Cut                   | P.03 Drag and Lift or Tipping          | S.03 Placed in a Bend                    |
| Lack of Pool/Pattern Development | F4. Bank Erosion at Vane       | P.04 Flow Expansion Out of Vane        | S.04 Placed on Bedrock                   |
| Lack of Dissipated Water Energy  | F5. Downstream Bank Erosion    | P.05 Piping                            | S.05 Arms not Tied in                    |
|                                  | F6. Insufficient Scour Pool    | P.06 Protected from Scour              | S.06 Arms too Short                      |
|                                  | F7. Downstream Streambed Scour | P.07 Side Cutting                      | S.07 Arms too Flat                       |
|                                  | F8. Lack of Pool Habitat       | P.08 Undercutting                      | S.08 Arms too Steep                      |
|                                  |                                | P.09 Weak Jet / Low Velocity Ratio     | S.09 Arms Washed Out                     |
|                                  |                                | P.10 Insufficient Energy Dissipation   | S.10 Sill too High                       |
|                                  |                                |  | S.11 Sill Washed Out                     |
|                                  |                                |  | S.12 Spacing of Boulders                 |
|                                  |                                |  | S.13 Boulders in Pool                    |
|                                  |                                |  | S.14 Undersized Boulders                 |
|                                  |                                |  | S.15 Drop too Short                      |
|                                  |                                |  | S.16 Drop too High                       |
|                                  |                                |  | S.17 Exposed Banks                       |
|                                  |                                |  | S.18 Insufficient Backfill               |
|                                  |                                |  | S.19 No footers                          |
|                                  |                                |  | S.20 Oversized Rock Cross Vane           |
|                                  |                                |  | S.21 Undersized Rock Cross Vane          |
|                                  |                                |  | S.22 Insufficient Pool Depth or Length   |
|                                  |                                |  | S.23 Structure too Steep                 |
|                                  |                                |  | S.24 Flow Not Concentrated in Center     |
|                                  |                                |  | S.25 Angle Between Arm and Bank too High |

**Table of Failure Mechanisms for Fish Passage**

|                      |                  |                            |                                |
|----------------------|------------------|----------------------------|--------------------------------|
| Lack of Fish Passage | F9. Fish Barrier | P.11 Debris blockage       | S.26 Channel too wide          |
|                      |                  | P.12. Shallow Water Depth  | S.27 Flow Constriction         |
|                      |                  | P.13. Excessive Turbulence | S.28 Channel too rough         |
|                      |                  | P.14. Water Surface Drop   | S.29 Drop in Channel Elevation |
|                      |                  |                            | S.30 Insufficient Base Flow    |

# Example of data form.

| Field Assessment Form for Step Pools   |                                      |  |
|--|--------------------------------------|--|
| Step Pool #  |                                      |  |
| Date   |                                      |  |
| Notes  |                                      |  |
| Score each indicator from 0 (indicator not present) to 5 (severe), circle each primary and secondary cause that is applicable. |                                      |  |
| Indicator  | Primary                              | Secondary                              |
| F1. Side Boulder Washout<br>Score ____   | P.03 Drag and Lift or Tipping        | S.01 Improper Alignment                |
|  |                                      | S.03 Placed in a Bend                  |
|  |                                      | S.12 Spacing of Boulders               |
|  |                                      | S.14 Undersized Boulders               |
|  |                                      | S.18 Insufficient Backfill             |
|  | P.08 Undercutting                    | S.01 Improper Alignment                |
|  |                                      | S.03 Placed in a Bend                  |
|  |                                      | S.16 Drop too High                     |
|  |                                      | S.18 Insufficient Backfill             |
|  |                                      | S.19 No footers                        |
| F2. Step Boulder Washout<br>Score ____   | P.03 Drag and Lift or Tipping        | S.10 Step too High                     |
|  |                                      | S.12 Spacing of Boulders               |
|  |                                      | S.14 Undersized Boulders               |
|  |                                      | S.18 Insufficient Backfill             |
|  |                                      | S.21 Undersized Step Pool              |
|  | P.08 Undercutting                    | S.02 Backed into a Pool                |
|  |                                      | S.16 Drop too High                     |
|  |                                      | S.18 Insufficient Backfill             |
|  |                                      | S.19 No footers                        |
|  |                                      | S.21 Undersized Rock Cross Vane        |
| F3. Head Cut<br>Score ____   | P.05 Piping                          | S.12 Spacing of Boulders               |
|  |                                      | S.18 Insufficient Backfill             |
|  | P.07 Side Cutting                    | S.01 Improper Alignment                |
|  |                                      | S.03 Placed in a Bend                  |
|  |                                      | S.05 Sides not Tied in                 |
|  |                                      | S.09 Sides Washed Out                  |
|  |                                      | S.10 Step too High                     |
|  | P.08 Undercutting                    | S.12 Spacing of Boulders               |
|  |                                      | S.21 Undersized Step Pool              |
|  |                                      | S.02 Backed into a Pool                |
| S.03 Placed in a Bend  |                                      |  |
| S.11 Step Washed Out   |                                      |  |
| F7. Downstream Streambed Scour<br>Score ____   | P.10 Insufficient Energy Dissipation | S.16 Drop too High                     |
|  |                                      | S.21 Undersized Step Pool              |
|  |                                      | S.22 Insufficient Pool Depth or Length |
|  |                                      | S.23 Structure too Steep               |
|  |                                      |  |

| Indicator                                   | Primary                                   | Secondary                              |                             |
|---|---|--|-----------------------------|
| F4. Bank Erosion at Structure<br>Score ____ | P.01 Direct Contact of Flow with Banks    | S.05 Sides not Tied in                 |                             |
|   |   | S.09 Side Boulders Washed Out          |                             |
|   |   | S.12 Spacing of Boulders               |                             |
|   | P.02 Flow Directed at Banks               | S.17 Exposed Banks                     |                             |
|   |   | S.01 Improper Alignment                |                             |
|   | P.05 Piping                               | S.03 Placed in a Bend                  |                             |
|   |   | S.12 Spacing of Boulders               |                             |
|   |   | S.18 Insufficient Backfill             |                             |
|   |   | P.07 Side Cutting                      | S.01 Improper Alignment     |
|   |   |  | S.03 Placed in a Bend       |
| S.09 Side Boulders Washed Out               |   |  |                             |
| S.10 Sill too High                          |   |  |                             |
| S.12 Spacing of Boulders                    |   |  |                             |
| P.08 Undercutting                           | S.21 Undersized Step Pool                 |  |                             |
|   | S.01 Improper Alignment                   |  |                             |
|   | S.03 Placed in a Bend                     |  |                             |
|   | S.16 Drop too High                        |  |                             |
|   | S.18 Insufficient Backfill                |  |                             |
| F5. Downstream Bank Erosion<br>Score ____   | P.02 Flow Directed at Banks               | S.19 No Footers                        |                             |
|   |   | S.21 Undersized Step Pool              |                             |
|   | P.04 Flow Expansion Out of Structure      | S.01 Improper Alignment                |                             |
|   |   | S.03 Placed in a Bend                  |                             |
|   | P.07 Side Cutting                         | S.13 Boulders in Pool                  |                             |
|   |   | S.21 Undersized Step Pool              |                             |
|   |   | S.01 Improper Alignment                |                             |
|   |   | S.03 Placed in a Bend                  |                             |
|   |   | S.05 Sides not Tied in                 |                             |
|   | F6. Insufficient Scour Pool<br>Score ____ | P.06 Protected from Scour              | S.09 Sides Washed Into Pool |
| S.11 Step Washed into Pool                  |   |  |                             |
| S.13 Boulders put in Pool                   |   |  |                             |
| P.10 Insufficient Energy Dissipation        |   | S.22 Insufficient Pool Depth or Length |                             |
|   |   | S.23 Structure too Steep               |                             |
| P.05 Piping                                 |   | S.12 Spacing of Boulders               |                             |
|   |   | S.18 Insufficient Backfill             |                             |
| P.09 Weak Jet                               |   | S.04 Placed on Bedrock                 |                             |
|   |   | S.11 Sill Washed Out                   |                             |
|   |   | S.15 Drop too Short                    |                             |
|   |   | S.20 Oversized Step Pool               |                             |

**We have successfully used this rapid assessment protocol for:**

**Step Pools**

**J-Hooks**

**Log Vanes**

**Rock Vanes**

**Regenerative Stormwater Conveyances**

**Fish Passages**

**Weirs**

**Riffle Grade Controls**



# **Case Study: Sullivan Branch**

**Headwater Stream Restoration Project**


**Construction completed in March, 2009**

**Location: Prince Frederick, Maryland**

**Physiographic Province: Western Coastal Plain**

**Length: 550 Linear Feet**

**Structures: 6 rock cross vanes, 4 rock J-hooks, and 7 step pools**



# **Structure Performance and Risk Analysis was integrated into the 5-year monitoring plan.**

- **Baseline assessment performed post-construction.**
  - **Assessment performed at the end of each monitoring year.**
  - **Currently in the third year of monitoring.**
- 10/27/2011 11:07

# Advantages

- **Able to identify construction changes**
- **Detailed inventory of channel adjustment around the structures**
- **Documented tipped boulders that might have gone unnoticed**



# Tracking both deterioration and improvement over time.

| Structure  | Date       | Failure Indicators Exhibited    | Failure Score (1-5) | Primary Causes Identified   | Secondary Causes Identified   |
|------------|------------|---------------------------------|---------------------|---|---|
| J-Hook     | April 2009 | Bank Erosion at Vane            | 1                   | Piping  | Insufficient Backfill   |
|            | Dec. 2009  | Bank Erosion at Vane            | 1                   | Flow Directed at Banks<br>Piping<br>Side Cutting                            | Placed in a Bend<br>Insufficient Backfill   |
|            |            | Downstream Bank Erosion         | 2                   | Flow Directed at Banks  | Improper Alignment  |
|            | Dec. 2010  | Bank Erosion at Vane            | 3                   | Direct Contact of Flow with Banks<br>Flow Directed at Banks<br>Undercutting | Exposed Banks<br>Improper Alignment<br>Placed in a Bend<br>Drop too High            |
|            |            | Downstream Bank Erosion         | 4                   | Direct Contact of Flow with Banks<br>Flow Directed at Banks<br>Weak Jet     | Exposed Banks<br>Improper Alignment<br>Flow not Concentrated in Channel Center      |
| Cross Vane | April 2009 | Insufficient Scour Pool         | 2                   | Protected From Scour<br>Weak Jet  | Cobbles Put in Pool<br>Arms too Flat<br>Drop too Short<br>Oversized Rock Cross Vane |
|            | Dec. 2009  | Insufficient Scour Pool         | 1                   | Weak Jet  | Drop too Short  |
|            | Dec. 2010  | No Failure Indicators Observed. |                     |   |   |

# Applications beyond use as a monitoring tool

- **Prioritizing structure rehabilitation projects**
- **Research applications (instead or in conjunction with flume studies)**
- **Stream response to structures**
- **Identify fatal flaws at design stage**
- **Better understanding of why particular structures are or are not achieving design goals**
- **Inform how projects are built in future**

10/08/2011 10:04

# Summary

- **Supplements traditional monitoring methods to give a multi-dimensional and detailed view.**
- **Provides consistent, quantitative results**
- **Flexible protocol can be used for a variety of structures or applications**
- **Provides information for future designs on the placement and use of certain structures, or improved specifications for construction**

## **Acknowledgements:**

**Maryland State Highway Administration**

**Field Crew: Matt Hubbard, Sumantha Prasad, Marcus Griswold**