



Green River flows (Jensen gage) peaked at 12,800 cfs on May 17, 2007. Levee breaches #1 and #2 no longer exist; they were filled to protect adjacent crop area. No photos were taken of the outlet downstream from levee breach #7. Levee breaches are located between river miles 305 and 306. Thunder Ranch is privately-owned; the Recovery Program has a perpetual easement.



Thunder Ranch Breach 4

No connection in 2007





Thunder Ranch Breach 5

No connection in 2007





Thunder Ranch Breach 6



No connection in 2007





Thunder Ranch Breach 7



No connection in 2007

