

Stewart Lake



No additional information. Unable to take measurements between 8,000 cfs (no inflow) and 11,200 cfs (19 cfs in 2006).

Photo taken from river looking towards the inlet gate (near river mile 300). The outlet gate was closed and the inlet gate opened on April 10, 2007. On 5/15/07, Green River (Jensen) flows increased from 10,800 cfs to 12,100 cfs. On May 29, 2007, the inlet gate was closed to prevent water from draining out of Stewart Lake as river flows declined. Stewart Lake is owned by Utah Division of Wildlife Resources.

Bonanza Bridge



No connection in 2007. Picture was taken at 12,200 cfs; however, even at 12,800 cfs on the 17th, the floodplain did not connect.

Bonanza Bridge (RM 290) has three upstream levee breaches and one downstream breach. The photo above was taken at upstream breach #2 which is currently the breach which connects at the lowest flow. The other three breaches were also checked and did not connect. Bonanza Bridge is owned by BLM.