

## 2023-2024 Hunt Blind Conditions

Please note that if blinds are listed as “unable to hunt,” you may still tie your boat to the existing structure to shoot. If blinds are listed as “poor,” please use caution.

### Pond A2E

1. Good - 2-3 person blind
2. Good - 2-3 person blind
3. Unable to hunt, partial sunken floor and broken beam, unstable
4. Unable to hunt, rebuild required
5. Good - 2-3 person blind
6. Unable to hunt, rebuild required
7. Unable to hunt, rebuild required
8. Good - 2-3 person blind
9. Poor
10. Good - 2-3 person blind
11. Fair - 2-3 person blind
12. Unable to hunt, rebuild required
13. Good - 2-3 person blind
14. Poor

### Pond AB1

15. Good - 2 person blind
16. Poor, unstable - 2 person blind
17. Good
18. Unable to hunt\*
19. Poor - 2-3 person blind\*
20. Unable to hunt\*
21. Unable to hunt\*
22. Unable to hunt\*
23. Unable to hunt\*

\*Water levels in Pond AB1 are very low and likely non-navigable. Not recommended to hunt.

### Pond AB2

24. Unable to hunt, rebuild required
25. Good 2-3 people
26. Unable to hunt, floor collapsed into water
27. Good - 2 person blind
28. Good - 2-3 person blind
29. Good - 2-3 person blind
30. Good - 2 person blind

### Pond A3N

1. Unable to hunt, unstable

**Pond A3W**

2. Good - 2-3 person blind
3. Good - 2-3 person blind
4. Good - 2-3 person blind
5. Good - 2 person blind
6. Good - 2-3 person blind
7. Good - 2-3 person blind
8. Fair - 2-3 person blind
9. Good - 2-3 person blind
10. Good - 2-3 person blind
11. Fair - 2 person blind
12. Fair - 2-3 person blind
13. Unable to hunt, sunken floor, unstable
14. Good - 2-3 person blind
15. Good - 2-3 person blind
16. Good, new 2-3 person blind
17. Good, new 2-3 person blind