



Landslide Areas Near the Hanford Reach National Monument

- Active Landslides
- Columbia River
- Major Roads
- Irrigation Wasteways
- County Boundaries
- Hanford Reach National Monument (Estimated Boundary)



The Monument boundary is based on the Federal Register Notice. BLM will fine-tune the boundary in the near future.

The Active Landslides shown may exclude small known landslides due to scale.

Background is a Landsat-7 Satellite Image, July 15 2002

Produced by the
Franklin Conservation District
PMD, September 2002

