



Johnson Bottom

	<p>051707 – River flow was 12,700 cfs. No significant inflow into downstream breach.</p>
<p>051607 - River flow was 11,900 cfs. No significant inflow into downstream breach.</p>	

Johnson Bottom is on the Ouray National Wildlife Refuge at river mile 261. The levee breach is on downstream end of wetland. River located on the right side of photos.

Old Charley Wash



Inflow into Old Charley-Main from inlet canal. River flow was 11,500 cfs. No significant inflow.

Downstream outlet – far from connection.



Inlet canal gate (located near Green River RM 252) was kept closed during 2007.
Downstream outlet is a swale near and upstream of the main gated outlet.
Old Charley Wash is on the Ouray National Wildlife Refuge.

Old Charley Wash



May 16, 2007 - 11,500 cfs. River back-flowing into wetland through fish kettle

May 17, 2007 - 12,700 cfs.

Main outlet canal (located near Green River RM 250). Second photo looking towards main wetland.