

## APPENDIX A

---

Project Area Photographs  
& Figures



**Figure 1 Looking upstream at the western spillway of Rattlesnake Brook Dam.**



**Figure 2 Eastern spillway of Rattlesnake Brook Dam.**



**Figure 3 Surface flow traversing floodplain from breach in eastern portion of Dam.**



**Figure 4 Looking upstream of Rattlesnake Brook Dam at the impoundment.**



**Figure 5 Looking upstream from the estuary at the new box culvert under Narrows Road.**



**Figure 6 Looking upstream at the western channel of Rattlesnake Brook from just upstream of Narrows Road.**




Figure 7 2014 Aerial photo of Rattlesnake Brook Restoration Project area in infrared color by USDA NAIP.




Figure 8 Contributing watersheds to the Rattlesnake Brook Dam.




Figure 9 MMI existing water surface profile output from HEC-RAS for base flow up through the 100-yr storm event in the western channel of Rattlesnake Brook (MMI 2014).




Figure 10 MMI predicted water surface profile output from HEC-RAS for base flow up through the 100-yr storm event in the western channel of Rattlesnake Brook (MMI 2014).