Photograph 1: Damaged Concrete Wall Along Walking Trail

Photograph 2: Cracking in Asphalt Walking Trail

Photograph 3: Walking Trail Looking Toward Lighthouse

Photograph 4: Slope Erosion Area Looking Toward Lighthouse

Photograph 5: Concrete Pulling Away From Edge of Concrete Wall

Photograph 6: Slope Erosion Area Looking Downhill